	Property is: Single F	amily		Duplex		Other ☑	<u>Condominium</u>	
Date:	7/1/2015							
ake no respo		ed after tl	he ins	pection dat	e, or fo	r omissions throug	the Redevelopment Authority, and their representatives gh error or oversight. The list does not necessarily inclu E programs.	
Exterior (Condition Report							
Location	Required Work			_		/Comments	Cost	
Site	Landscaping Stand/Landraile			Yes □	Self F	негр	\$	
	Steps/Handrails		<u> </u>	Yes 🗆			\$	
	Service walks	n/a		Yes □			\$	
	Fencing			Yes 🗆			\$	
	Parking		<u> </u>	Yes 🗆			\$	
	Retaining walls		<u> </u>	Yes 🗆			\$	
	Other	n/a		Yes 🗆			\$	
Garage	Other	n/a	a 🗆	Yes 🗆			\$	
	Singles: repair	n/a	a 🗆	Yes □			\$	
	Shingles: Roof over existin	g n/a	a 🗆	Yes □			\$	
	Shingles:Tear off & re-roof	n/a	a 🗆	Yes □			\$	
	Gutters/downspouts	n/a	<u> </u>	Yes □			\$	
	Flashing	n/a	a 🗆	Yes □			\$	
	Eaves	n/a	a 🗆	Yes □			\$	
	Siding	n/a	a 🗆	Yes □			\$	
	Doors	n/a	a 🗆	Yes □			\$	
	Windows	n/a	a 🗆	Yes □			\$	
	Slab	n/a	a 🗆	Yes □			\$	
	Paint	n/a	a 🗆	Yes □			\$	
	Electrical	n/a	a 🗆	Yes □			\$	
	Other	n/a	a 🗆	Yes □			\$	
Porches	Roof	n/a	a 🗆	Yes □			\$	
	Deck-upper	n/a	a 🗆	Yes 🗆			\$	
	Decklower	n/a	a 🗆	Yes 🗆			\$	
	Steps/handrails	n/a	a 🗆	Yes 🗆			\$	
	Ceiling	n/a	a 🗆	Yes 🗆			\$	
	Guardrails	n/a	a 🗆	Yes 🗆			\$	
	Structural	n/a	a 🗆	Yes □			\$	
	Paint	n/a	a 🗆	Yes 🗆			\$	

\$

n/a □ Yes □

Scope of Work for Property Located at: 9050-D North 95th Street

Other

House

Chimney	n/a □	Yes □	\$
Shingles: repair	n/a □	Yes □	\$
Shingles: Roof over existing	n/a □	Yes □	\$
Shingles:Tear off & re-roof	n/a □	Yes □	\$
Gutters/downspouts	n/a □	Yes □	\$
Flashing	n/a □	Yes □	\$
Eaves	n/a □	Yes □	\$
Siding	n/a _□	Yes □	\$
Storm Doors	n/a □	Yes ☑	\$ 300.00
Prime ("main") Doors	n/a □	Yes □	\$
Storm Windows	n/a □	Yes □	\$
Prime ("main") Windows	n/a □	Yes □	\$
Paint	n/a □	Yes □	\$
Foundation	n/a _□	Yes □	\$
Electrical	n/a □	Yes □	\$
Other	n/a □	Yes □	\$
Other	n/a □	Yes □	\$
Other	n/a 🔲	Yes 🗆	\$
Other	n/a □	Yes □	\$

Exterior: Estimated Cost:* \$ 300.00
*average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report Unit: Entire unit (single family)				Lower unit of duplex		
Mechanical Heating	Upper unit of duplex Required Work				Condo		
3	Repair/replace boiler	n/a ☑	Yes			\$	
	Repair radiation	n/a ☑	Yes	; <u> </u>		\$	
	Repair/replace furnace	n/a <u></u>	Yes	; <u> </u>	<u> </u>	\$	
	Repair ductwork	n/a ☑	Yes	; <u> </u>		\$	
	Replace thermostat	n/a ☑	Yes	<u> </u>	_	\$	
	Repair/replace grilles	n/a ☑	Yes	; <u> </u>		\$	
Electrical	Tune boiler/furn. insp ht exchang	€n/a □	Yes	V		\$	350.00
Licotrical	Repair/replace receptacles	n/a ☑	Yes	; <u> </u>	_	\$	
	Repair/replace switches	n/a ☑	Yes	<u> </u>		\$	
	Repair/replace fixtures	n/a □	Yes	· •		\$	250.00
	Install outlets and circuits	n/a □	Yes	· •	_	\$	500.00
	Install outlets and circuits	n/a ☑	Yes	; <u> </u>		\$	
	Install outlets and circuits	n/a ☑	Yes	; <u> </u>		\$	
	Install outlets and circuits	n/a ☑	Yes	; <u> </u>		\$	
	Upgrade service	n/a _☑	Yes	; <u> </u>		\$	
Plumbing	Other	n/a □	Yes	; <u> </u>	_	\$	
	Other	n/a □	Yes	<u> </u>	_	\$	
Fluinbing	Repair/replace kitchen sink	n/a □	Yes			\$	
	Repair/replace kitchen sink fauce	e n/a _□	Yes	<u> </u>	_	\$	
	Repair/replace tub	n/a ☑	Yes	; <u> </u>		\$	
	Repair/replace tub faucet	n/a 🗹	Yes			\$	
	Repair/replace toilet	n/a 🗆	Yes	· 🗸	_	\$	300.00
	Repair/replace lavatory	n/a _☑	Yes	; <u> </u>		\$	
	Repair/replace lavatory faucet	n/a ☑	Yes	<u> </u>	_	\$	
	Repair/replace wash tub	n/a ☑	Yes			\$	
	Repair/replace wash tub faucet	n/a 🗵	Yes		<u></u>	\$	
	Unclog piping:	n/a ☑	Yes		_	\$	
	Repair drain/waste/vent piping	n/a 🗹	Yes			\$	
	Repair water piping	n/a 🗹	Yes		_	\$	
	Repair/replace water heater	n/a 🔽	Yes		_	\$	
	Other	n/a □	Yes	· •	Complete Kitchen	\$	1,800.00

\$

Other

Windows								
	Replace broken glass	n/a	1	Yes			\$	
	Repair or replace sash	n/a	1	Yes			\$	
Doors	Repair or replace doors	n/a	7	Yes		==	\$	
	Repair or repl. locks/latches	n/a		Yes	4	Self Help	\$	60.00
Walls/Ceiling	s Repair or repl. @ defective	n/a		Yes	7		\$	900.00
Paint	<u> </u>							
	Repair or repl. @ defective	n/a		Yes	4	_	\$	1,500.00
Fire Safety			_			=		
,	Install smoke/CO alarm:bsmt.	n/a		Yes	1	Self Help	\$	60.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	7	Self Help	\$	60.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	7	Self Help	\$	60.00
Handrails	Repair/replace defective	n/a		Yes	П	Self Help	\$	
Stairs	Tropulinopiado de locuro	.,,					Ψ	
Floors	Repair defective	n/a	4	Yes			\$	
FIOUIS	Repair defective	n/a	П	Yes	V		\$	1,200.00
Other	. Topan dolocaro	.,, u						
		n/a		Yes	✓	Millwork	\$	500.00
		n/a		Yes	7	Hardpipe dryer vent	\$	125.00
		n/a		Yes			\$	
		n/a		_Yes			\$	
						Interior: Estimated Cost:	\$	7,665.00
						Total Exterior and Interior Cost:*	\$	7,965.00

Inspected by: Mark Stack Date: 7/1/2015

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located on the first floor of 841 N. Broadway.

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.